

Comox Valley Airport Operations Manager Directive

Directive number: 2010-008

Date: 17 Dec 2010

To: Air Carriers

CC: Airline Support Services

Subject: Aircraft De-icing Reporting to 19 Wing Operations

Reference: 19 Wing Flying Orders Ch 8 Chapter 4 A/C Deicing procedures and Env Monitoring

- 1. In accordance with the referenced 19 Wing Flying Orders, as part of the Environment Canada requirement to monitor, record and control the amount of glycol which flows to surface water all aircraft de-icing on the CVAC Ramp needs to be reported each time it is completed. To accomplish this, the Air Carrier shall report: the location of the aircraft and the total amount of deicing fluid used to 19 Wing WOC (250) 339-8231 after completing any aircraft de-icing activity. CVAC staff shall take the appropriate action should the De-icing Mitigation Plan be put into effect. The following procedures shall take effect immediately.
- 2. For questions or clarification do not hesitate to contact the undersigned.

Ian Heselgrave YQQ Operations Manager Phone: (250) 339-3044

E-mail:operations@comoxairport.com

Distribution List:

CVAC Operations Staff
CVAC Maintenance Staff
CVAC CEO
WestJet Station Manager
Pacific Coastal Station Manager
Central Mountain Air Station Manager



Budget
National
On the Fly Café
Mid Island Gifts
Airline Support Services
DND AMU Staff
Garda Base Administrator